Maryland Historical Trust

Maryland Inventory of Historic Properties number: 6-1-1-7

Name: 11023/USZ1900en Cho	rry Creek			
The bridge referenced herein was inventoried by the Maryland Historic Bridge Inventory, and SHA provided the Trust with el The Trust accepted the Historic Bridge Inventory on April 3, 2 determination of eligibility.	State Highway Administration as part of the ligibility determinations in February 2001.			
MARYLAND HISTORICAL TRUST Eligibility Recommended Eligibility Not Recommended X				
Criteria:ABCD Considerations:A Comments:	BCDEFGNone			
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001			
Reviewer, NR Program: Peter E. Kurtze	Date:3 April 2001			

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/ MARYLAND HISTORICAL TRUST

SHA Bridge No. 11023 Bridge name U.S. 219 over Cherry Creek
LOCATION: Street/Road name and number [facility carried] U.S. 219 (Elkins-Oakland Road)
City/town Gortner Vicinity X
County Garrett
This bridge projects over: Road Railway Water X Land
Ownership: State X County Municipal Other
HISTORIC STATUS: Is the bridge located within a designated historic district? Yes No _X National Register-listed district National Register-determined-eligible district Locally-designated district Other
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete
Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder : Rolled Girder Concrete Encased Plate Girder Concrete Encased Plate Girder Concrete Encased : Plate Girder Concrete
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X : Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name

DESCRIPTION:			
Setting: Urban	Small town	Rural	_X

Describe Setting:

Bridge No. 11023 carries U.S. 219 (Elkins-Oakland Road) over Cherry Creek in Garrett County. U.S. 219 runs north-south and Cherry Creek flows east-west. The bridge is located in the vicinity of Gortner and is surrounded by farmland and a commercial property.

Describe Superstructure and Substructure:

Bridge No. 11023 is a 2-span, 2-lane concrete slab bridge. The bridge was built in 1922 on existing stone abutments, however, the date of construction of the earlier bridge is unknown. In 1922, the original abutments were extended with concrete and the wing walls were rebuilt with stones from the original wing walls; the current concrete slab superstructure was constructed on this reconfigured substructure. The 1922 parapets have been removed and the wing walls have been covered with gunite, however, it is not known when this occurred. The structure is 45 feet long and has a clear roadway width of 24 feet; there are no sidewalks. The out-to-out width is 25 feet, 4 inches. The concrete slab is 1 foot, 9 inches thick, and it has a bituminous wearing surface. The structure has steel guard rails and the roadway approaches have no shoulders and steel guard rails. The substructure consists of two (2) concrete abutments and gunite-covered stone wing walls. The northwest and southeast wing walls are flared, and the northeast and southwest wing walls are ushaped. The bridge is not posted, and has a sufficiency rating of 58.6.

According to the 1995 inspection report, this structure was in fair condition with numerous cracks and severe concrete spalling at the expansion joints. The asphalt wearing surface has depressions in the traffic lanes. The concrete is scaling throughout the surface and is spalling severely at the joints. The concrete abutments and stone wing walls have had numerous gunite patches applied.

Discuss Major Alterations:

The bridge was constructed in 1922 on existing abutments. The abutments were extended with concrete and the wing walls were built with stone from the original wing walls. The parapets built in 1922 have been removed and the wing walls have been covered with gunite, however, the date of the alterations are unknown. There have been no other alterations.

WHY was the bridge built?

HISTORY

The bridge was constructed in response to the need for a more efficient transportation network and increased load capacity.

WHO was the designer?

State Roads Commission

WHO was the builder?

State Roads Commission

WHY was the bridge altered?

The bridge was altered to correct functional or structural deficiencies.

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have Na	ational Register significanc	e for its association with:
A - Events	B- Person	
C- Engineering/a	rchitectural character	

The bridge does not have National Register significance.

Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-1904 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's. Most improvements to local roads waited until the years after World War I.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer, stated in 1906, "the general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do away with the further expense

of the maintenance of expensive and dangerous wooden structures." Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

In 1930, the roadway width for all standard plan bridges was increased to 27 feet in order to accommodate the increasing demands of automobile and truck traffic (State Roads Commission 1930). The range of span lengths remained the same, but there were some changes designed to increase the load bearing capacities. The reinforcing bars increased in thickness. Visually, the 1930 design can be distinguished from its predecessors by the pierced concrete railing that was introduced at this time.

In 1933, a new set of standard plans were introduced by the State Roads Commission. This time their preparation was not announced in the <u>Report</u>; new standard plans were by this time nothing special - they had indeed become standard. Once again accommodating the ever-increasing demands of traffic, the roadway was increased, this time to 30 feet. The slab span's reinforcing bars remained the same diameter but were placed closer together to achieve still more load capacity.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

A significant example of a concrete slab bridge should possess character-defining elements of its type, and be readily recognizable as an historic structure from the perspective of the traveler. The integrity of distinctive features visible from the roadway approach, including parapet walls or railings, is important in structures which are common examples of their type. In addition, the structure must be in excellent condition. This bridge, which is lacking such features as the original concrete parapets, is an undistinguished example of a concrete slab bridge.

Does the bridge retain integrity of important elements described in Context Addendum?

This bridge was altered at an unknown date, resulting in the loss of such character-defining elements as the original parapets.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?


This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

B	ΙB	LI	O	GR.	AP	HY:	
---	----	----	---	-----	-----------	-----	--

County Other	y inspection/bridge files (list):	SHA inspection/bridge files X
Ketchu 1908	um, Milo S. The Design of Highway Bridges and th	ne Calculation of Stresses in Bridge Trusses. The
	Engineering News Publishing Co., New	•
1920	The Design of Highway Bridges of Steel, T Book Company, New York.	Fimber and Concrete. Second edition. McGraw-Hill
Lay, M	laxwell Gordon	
1992		orld's Roads and of the Vehicles That Used Them. ck, New Jersey.
Maryla	and State Roads Commission	
1930a	Report of the State Roads Commission of Maryland, State Roads Commission, Ba	for the Years 1927, 1928, 1929 and 1930. State of altimore.
1930b	Standard Plans. State of Maryland, State	e Roads Commission, Baltimore.
Taylor, 1939	r, Frederick W., Sanford E. Thompson, an Reinforced-Concrete Bridges with Formula Wiley & Sons, Inc., New York.	nd Edward Smulski as Applicable to Structural Steel and Concrete. John
Tyrrell	l, H. Grattan	
1909	Concrete Bridges and Culverts for Both	h Railroads and Highways. The Myron C. Clark
	Publishing Company, Chicago and New	York.
<u>SURVI</u>	EYOR:	
Date b	oridge recorded3/3/97	
	of surveyor Caroline Hall/Ryan McKay	
_	ization/Address P.A.C. Spero & Co., 40 V	W. Chesapeake Avenue, Baltimore, MD 21204




INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: Bridge #11023 Survey Number: $G \rightarrow V - A - /77$
Project: <u>US 219 over Cherry Creek, Garrett County</u> Agency: <u>SHA</u>
Site visit by MHT Staff: X no yes Name Date
Eligibility recommended Eligibility not recommended
Criteria:AB <u>X</u> CD Considerations:ABCDEFGNon
Justification for decision: (Use continuation sheet if necessary and attach map)
According to information prepared by SHA, Bridge #11023, a concrete slab structure composed of two 22' spans, constructed in 1922, does not meet the National Register criteria for individual listing. Concrete slab structures such as this were common by the 1920s and Bridge #11023 has no particular historical or engineering significance. Numerous examples of similar bridges remain in the state. Bridge #11023 is not located in any known district.
Documentation on the property/district is presented in: <u>Project files</u> Preparedby: <u>RitaSuffness</u>
Elizabeth Hannold February 20, 1992
Reviewer, Office of Preservation Services Date
NR program concurrence: V yes no not applicable Reviewer, NR program Date

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I.	Geographic Region:				
	Eastern Shore Western Shore	<pre>(all Eastern Shore counties, and Cecil) (Anne Arundel, Calvert, Charles, Prince George's and St. Mary's)</pre>			
	Piedmont	(Baltimore City, Baltimore, Carroll, Frederick, Harford, Howard, Montgomery)			
_X	Western Maryland	(Allegany, Garrett and Washington)			
II.	Chronological/Developmental Pe	eriods:			
	Paleo-Indian Early Archaic Middle Archaic Late Archaic Early Woodland Middle Woodland Late Woodland/Archaic Contact and Settlement Rural Agrarian Intensification Agricultural-Industrial Trans Industrial/Urban Dominance Modern Period Unknown Period (prehiste	ition A.D. 1815-1870 A.D. 1870-1930 A.D. 1930-Present			
III.	Prehistoric Period Themes:	IV. Historic Period Themes:			
	Subsistence Settlement Political Demographic Religion Technology Environmental Adaption	Agriculture X Architecture, Landscape Architecture, and Community Planning Economic (Commercial and Industrial) Government/Law Military Religion Social/Educational/Cultural Transportation			
V. F	lesource Type:				
	Category: <u>Structure</u>				
	Historic Environment: _rural				
	Historic Function(s) and Use(s): <u>transportation</u>				
	Vacuus Danidan Courses university	in .			
	Known Design Source: <u>unknow</u>				





3 Sarrett Lo MO 4 Fran Me say 5 3/47 6 MA SHAS 8. 108 2



2 18 214 beer Cherry Preck Larrett Le Mo 1 Run mi sus



Mb T lestreum exvahin 9. 3 4 5



2 Us I I was proper to North approach 2015



2 US 219 Over Charm Creek 23 3 June H L Mal